D0 Shift Captains Responsibilities

Trainings:

- Rad worker
- D0 Hazard Awareness
- Controlled access
- ♦ LOTO I
- Shift Captain training
- ◆ 2 joint shifts with experienced Captain

Responsibilities

- ◆ Reports to Run coordinator
- Serves as single point of contact between DO and MCR crews
- ◆ Maintains order in the DO control room
- Understands the run plan and directs shift accordingly
 - ♦ http://www-d0.fnal.gov/~d0run/
- ◆ Issue orders for
 - Begin/end store
 - ◆ Begin/end runs
- Fill: a) shift, b) store, c) run checklists and directs other shift members to perform required checklists
- Ensures shift turnover meetings address important items
- Assist Controlled Access Coordinator during Controlled Access
- Supervised access issue/receive supervised access keys, verify training
- ♦ Monitor SMT radiation dose using ACNET
- Respond to system related alarms (contact ops shifters and/or experts, etc.)
 - ▲ Radiation dose to silicon
 - ▲ DMACS and cryogenic alarms
 - ▲ FIRUS alarms
 - ▲ SES alarms
- ♦ Execute appropriate emergency response procedures in emergency situations (contact x3131, contact experts, etc.)
- Direct operation of magnets power supplies by Ops following magnets polarities plan and daily run plan
- ◆ Operate luminosity counters HV according to instructions
- Order detector shifters to set HV according to the run plan
 - Special attention to SMT HV
- ◆ Run ACNET beam monitoring (luminosity, beam halo, etc.)
- Run vertex Examine
- ◆ Update electronic logbook during shift
- ◆ Issue temporary TLD badges